CASIO®

4249252

G-SHOCK

GD-120 Specifications

⇒ **Mineral Glass**
⇒ **5 Alarms**
⇒ **Timer**
⇒ **Stopwatch**
⇒ **Auto LED Light**
⇒ **World Time**
⇒ **Flash Alert**
⇒ **200M WR**

Alarm Indicators– Flash Alert Indicator

Auto Light Indicator

Model variations may differ in appearance from the example above.

World Time	Displays the current time in major cities and specific areas	Press button **C** until display shows WT. Scroll through the pre-set cities using button **D**. The Local time will be displayed for each city. To swap your home and world time cities, in World Time mode press buttons **A** and **B** simultaneously.
Stop Watch	Elapsed time, split time and final time are measured with 1/100-sec accuracy. The watch can measure times of up to 24 hrs.	
Countdown Timer	A stopwatch that counts backwards: When 0 minutes, 0 seconds is reached, the timer emits a 10-second signal tone.	Press button **C** until TMR is displayed. Press and hold button **A** to unlock the watch, Press **C** to scroll through the flashing fields using button **D** to alter where required. Lock your settings with button **A** then start/ stop the timer with button **D**. When stopped you can reset the timer with button **A**.
5 Alarms	The daily alarm reminds you about recurring events with an acoustic signal at the time you have set. You can also activate hourly time signals (SIG). This model has 5 inde-pendent alarms which can be set to sound once only or on a daily basis.	Press button **C** until the digital displays shows ALM. Choose which of the 5 alarms to set using button **D**. Once chosen, press and hold button **A** to unlock the setting function. Press **C** to chose whether to set the hours or the minutes, and set that section with button **D**. Press button **A** lock your settings and then use button **A** again to turn alarm on or off (1-ON= one time alarm)

Auto Light	The back light automatically illuminates the watch face each time the watch is tilted 40 degrees. Activate this feature by pressing and holding button **B** until the LT indicator turns on.
Flash Alert	When flash alert is turned on the illumination flashes for alarms. Hold **A.** until seconds flash, press **C.** ten times, press **D.** to toggle flash alert on and off.
Mineral Glass	Artificially manufactured glass with improved level of hardness and scratch resistance.
Water resistant 200m	Perfect for free diving without scuba equipment.