



Stop Watch	1/100-sec accuracy.	Press B until display shows stopwatch mode (ST). The stopwatch continues to run, restarting from zero after it reaches its limit (59.99 seconds), until you stop it. The stopwatch measurement continues operation even if you exit the Stopwatch mode. Use following to measure times with the Stopwatch. To measure times with the stopwatch (a) Elapsed time measurement (a) Elapsed time measurement (b) Split time measurement (b) Split time measurement (c) Start Split clisplayed) Start Split release (a) Elapsed time measurement (b) Split time and 1st-2nd place times (c) Split time and 1st-2nd place times (c) Split time and 1st-2nd place times (c) Split time and 1st-2nd place times (a) Elapsed time of first runner First runner.
Alarm	Allows you to specify the hour, minutes, day and month of the alarm.	In Alarm Mode, Press C, the hour digits will automatically flash indicating the alarm is turned on. Press C to change the digit selection across the hour digits, and minute digits. Once minutes are completed Press C, no digits will flash and you return to Alarm Mode. If you do not operant any button for one or minutes while a digit selection is flashing, the flashing will stop and watch returns to Time Keeping Mode automatically.
Water Resistant	Suitable to resist light splashing.	Water Resistant classification DIN 8310 / ISO 2281 is only resistant to minor splashing.
LED Light	In any mode Press C to illuminate display	·